

Replacement Sheet

1/10




Figure 1




Figure 2



Replacement Sheet

2/10




Figure 3

Replacement Sheet

3/10




Figure 4 (i-v)

Replacement Sheet





Figure 4 (vi-x)



Replacement Sheet

5/10




Figure 5 (i-v)

Replacement Sheet

6/10




Figure 5 (vi-xi)

Replacement Sheet

7/10




Figure 6 (i-vi)

Replacement Sheet

8/10

Side View





Figure 7 (i-viii)

Replacement Sheet

9/10


Side View

(i)



Step 1


(ii)



Coat A
Coat resist R


Step 2

(iii)



Pattern resist
Step 3


(iv)



Transfer resist
slope by etching
resist and A

Step 4

(v)



Step 5

Figure 8 (i-v)

Replacement Sheet

10/10

Side View




Figure 9 (i-v)